



Features:

- 1. DW01 Weighs a wide range of flexible and rigid packs up to 1kg.
- 2. Excellent accuracy, especially with flexible packaging.
- 3. Fast Belt speeds up to 40 m/min.
- 4. Reliable heavy duty conveyor components, high quality electronics.
- 5. Easy to use full color graphical touch screen.
- 6. Environment wide operating temperature range 0-40°C.

Check weighers are automatic machines to check the weight of packaged commodities. It is used at the off-going end of a production process and is used to ensure that the weight of a pack of the commodity is within specified limits. Any packs that are outside the tolerance are taken out of line automatically.